



PRODUCT BULLETIN

TO: DISTRIBUTORS AND FRANCHISES

DATE: February 21, 2018

2017-2018 Chevrolet Colorado / GMC Canyon 3.6L Oil Filter Removal

When removing the oil filter on a 2017-2018 Chevrolet Colorado or GMC Canyon equipped with the 3.6L engine, do not remove the standpipe located in the filter housing.



The routing of the A/C hose and other hoses interfere with the removal of the oil filter. Precaution must be taken not to remove the standpipe from the filter housing. It can easily come out with the removal of the filter and go unnoticed if the technician is not observant.



Installing an oil filter without the stand pipe in the housing can result in major engine damage. If removed or broken, the standpipe cannot be replaced. A new filter housing, which is currently on backorder from GM, will have to be purchased and installed.

For further information please contact Scott Hunsinger at MOA.